
30–0400 Retrofitting Accelerator Control Shaft and Bearing Bracket (SA only)

Preceding work:

Operation no. of operation texts and work units or standard texts and flat rates:



Model 126 Engine 603.96 (SA) effective Model Year 1986

A modified accelerator control shaft with bearing bracket can be retrofitted to eliminate accelerator pedal vibration.

Only the modified accelerator control is still available in the Parts Sector.

Note

The bearing points and ball sockets of the accelerator control should be greased with DB anti-corrosion grease 000 989 87 57 10 with the exception of the link between the accelerator control shaft (244) and lever (249).

List of parts

| | | W. W | |
|----------|------|--|---------------------|
| Quantity | ltem | Designation | Part No. |
| 1 | 248a | Locking element | 912 007 00 80 00 |
| 1 | 248b | Teflon washer | 123 301 01 76 |
| 1 | 248 | Bearing bracket | 126 301 16 40 |
| 3 | 248c | Screw | 914 125 00 63 04 02 |
| 3 | 248d | Washer | 000 125 00 64 21 |
| 1 | 248e | Corrugated washer | 900 055 00 80 02 |
| 1 | 249 | Lever | 126 300 46 25 |
| 1 | 249a | Locking element | 123 301 02 73 |
| 1 | 244 | Accelerator control shaft | 126 300 57 20 |
| 1 | 203 | Profile rod | 000 070 59 75 |
| | | Repair kit | 126 300 58 20 |

Note

With the engine switched off, depress accelerator pedal as far as stop on the kickdown switch from the interior of the car. The control lever of the injection pump must move against the full throttle stop (arrow). Adjust profile rod, if necessary. It is essential to ensure that the accelerator control moves freely.

