Note

The material quality of the coolant and heating hoses has been improved as of 10/1993. Identification DBL 6254.12 (was DBL 6254.11). When performing repairs or replacing the engine etc., install the improved hoses.